

OSA -5413-64

LN 2060

24 November 1964

25X1A

TO:

[REDACTED]

FROM:

SUBJECT: Service Bulletin HC-73B-SB39 and HC-73B-SB39-2

1. Following is background information on above Service Bulletins.
2. Service Bulletin-39 is being re-issued with up-dated information to assure best possible installation of mounts. The -2 kit supplements this bulletin by providing the modified plates required to make the new assembly. The -1 supplement will remain active until all mounts have been modified per these instructions.
3. Dash Two kits are being forwarded to [REDACTED] or immediate issue to Project Detachments, particularly Detachment H. Kits for FOG will follow as soon as more modified plates are available.

25X1A

25X1A

[REDACTED]

AJB
25X1A

cc: